

FIG. 1




FIG. 2

FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 2




FIG. 3




FIG. 9




FIG. 10




FIG. 11




FIG. 13

POSITION	TAG CODE	SERIAL NO.	ITEM DESCRIPTION	SSL	OWNER	ROT	NON-ROT	TOTAL	FTG
10	49339764	DS12/5/9628	5in Hevi-wate, NC-50	29.5	GMDC	431.05	10.09	8309	
9	47620872	DS12/5/9632	5in Hevi-wate, NC-50	30	N/A	.05	2.09	309	
8	17455466	DS12/5/9645	6in Strng Drill Colar	28.5	N/A	.05	.09	85	
7	49139370	DS12/5/9657	6in Strng Drill Colar	31	N/A	.05	2.09	309	
6	49314672	DS12/5/9659	6in Strng Drill Colar	30.5	N/A	.05	.09	85	
5	49146570	DS12/5/9651	8in x 6 in X-over sub6	4	N/A	.05	2.09	309	
4	49146570	DS12/5/9656	8in Slick String Drill	31	N/A	.05	.09	85	
3	49107573	DS12/5/9620	8in Slick String Drill	31	N/A	.05	2.09	309	
2	49261869	DS12/5/9656	8in Slick String Drill	31	N/A	.05	.09	85	
1	491447NA	DS12/1/9610	12 1/4 Rock Bit	3	N/A	.05	.09	85	

TUBE:	BHA:	TOTAL:	TRIP	TD
206	208	210	212	214

Manufacturer's Data	Inspection Data	Remove	Add	Replace
Bottom Hole Assembly	Vender Data	STRG. Report	Rentals	Close




FIG. 14




FIG. 15




FIG. 16